Antigo Job #	Location	Year	Concrete Rubblized (square yards)	Thickness of Existing Concrete (inches)	Overlay Type	Overlay Thickness (inches)	Comments
1857	Rantoul Airport, IL, R/W 18-36 & T/W 'F'	1999	45,670	6-8	НМА	5	Demonstrated 3 maximum surface sizes: 3", 9" & 18"
1857	Kantour Anport, IL, N/w 10-50 & 1/w 1	1999	45,070	0-8	IIIviA	5	Demonstrated 5 maximum surface sizes. 5 , 7 & 10
2074	Columbus Airport, IN, T/W 'C' & West Apron Taxilane	2000	24,975	6	HMA	7.5	
2205	Watertown Airport, SD, Apron Area	2001	39,456	8	HMA	4	Asphalt millings (3") placed prior to HMA overlay
2267	Rantoul Airport, IL, R/W 9-27	2001	3,625	6-8	HMA	4.6	
2369	Kalamazoo/Battle Creek Airport, MI, T/W 'E'	2002	5,250	8	HMA	11.5	
2455	Selfridge Air National Guard Base, Detroit, MI, R/W 01-19	2002	95,706	13-21	HMA	7	21" concrete is 11" bonded over 10", crushed aggregate (4.5") placed for grade correction
2562	IN Air National Guard Base, Ft. Wayne, IN, Parking Ramp & T/W	2003	25,258	10	JPCP	13	
2665	Watertown Airport, SD, Hanger Area	2003	1,982	6	HMA	3	Asphalt millings (3") placed prior to HMA overlay
2835	Ephrata Airport, WA, R/W 11-29 & T/W B-2	2004	26,500	6	НМА	4	
2970	Columbus Airport, IN, T/W 'E'	2004	12,768	6	HMA	7	
2976	Capital Airport, Springfield, IL, R/W 4 Overrun	2005	15,000	10	НМА	3	
3084	Grand Forks Air Force Base, ND, R/W 17-35	2005	237,558	19-24	HMA	9	Crushed aggregate (4-13") placed for crown correction
2938	Buffalo Niagara Airport, NY, T/W 'A'	2005-06	21,562	11	НМА	8	
3183	San Juan International Airport, Puerto Rico, R/W 10-28	2005-07	147,143	15	РССР	16	Crushed aggregate (3-6") placed prior to concrete overlay
3162	Pierre Airport, SD, R/W 13-31 Blast Pad	2005	4,984	9	НМА	4	
3149	Toledo Metcalf Field, OH, R/W 4-22	2006	29,542	6	HMA	3	Crushed aggregate (variable) placed prior to HMA overlay

Antigo Job #	Location	Year	Concrete Rubblized (square yards)	Thickness of Existing Concrete (inches)	Overlay Type	Overlay Thickness (inches)	Comments
					<u> </u>		
3246	Detroit Metro Airport, MI, Connector W-1	2006	625	17	HMA	5-9	Feasibility test for Detroit Metro runways & taxiways
3547	Tullahoma Airport, TN, Runway	2007	1,000	7	n/a	n/a	Demonstrate rubblization for 3 subgrade conditions.
3824	Dayton Int'l Airport, OH, T/W J & H	2007	6,000	6	HMA	10	Crushed aggregate (6") placed prior to HMA overlay
	King Abdulaziz International Airport (KAIA), Jeddah, Saudi Arabia.	2008-12	1,560,000	12-17	HMA	10	
4108	Nashville International Airport, TN, R/W 2L-20R	2009	3,600	16	РССР	15	Crushed aggregate (4") and HMA (4") placed prior to concrete overlay.
3871	Travis Air Force Base, CA, R/W 21L-03R	2010	134,000	14-21	РССР	14	Crushed aggregate (minimum 4") placed prior to concrete overlay
	Chhatrapati Shivaji International Airport, Mumbai, India, T2 Apron	2010-11	93,393	16	РССР	16	"Black sand" layer (variable) placed prior to concrete overlay.
4203	F.S. Gabreski Airport, Southampton, NY, R/W 6-24	2010	25,750	9	HMA	6	
4220	Eastern Iowa Airport, Cedar Rapids, IA, R/W 9/27	2010	80,417	8-17	РССР	16	Cement treated base (1") over crushed aggregate (2") placed prior to concrete overlay
4246	Sterling Airport, CO, Rehabilitate R/W 15/33	2010	38,180	6	HMA	6	
4339	Cleveland Hopkins Airport, OH, R/W 10-28 (28 end)	2011	29,790	11-16	РССР	14	Stabilized base (8") placed prior to concrete overlay.
4397	Cleveland Hopkins Airport, OH, R/W 10-28 (10 end)	2011	15,600	11	РССР	14	Crushed aggregate (variable) and stabilized base (8") placed prior to concrete overlay.
4485	Great Falls International Airport, MT, taxilane	2011	7,645	7	HMA	4	
4516	Oklahoma Air National Guard, Tulsa, OK, parking apron	2012-13	36,477	11	РССР	12	Crushed aggregate (variable) and HMA base (3") and stabilized drainage layer (4") placed prior to concrete overlay.
4569	Atlantic City International Airport, NJ, emergency access roads	2012	6,438	12	HMA	4+	
4591	Niagara Falls International Airport, NY, R/W 10L-28R	2012	85,644	7-10	HMA	8-8.5	Millings leveling course (0"-2") placed prior to asphalt overlay.

Antigo Job #	Location	Year	Concrete Rubblized (square yards)	Thickness of Existing Concrete (inches)	Overlay Type	Overlay Thickness (inches)	Comments
					21		
4749	Walla Walla Airport, WA, Apron Rehabilitation	2013	57,434	11	HMA	5	
4799	McConnell AFB, Wichita, KS, Repair T/W Alpha - North	2013-14	37,269	10-15	РССР	19	Rubblization is of lower layer after upper layer and asphalt removed and lower layer milled to provide 23" depth below original grade. Crushed aggregate (4") placed prior to concrete overlay.
4817	Griffiss Intl Airport, Rome, NY, Rehab Taxiways	2013	52,610	16-24	HMA	5	Concrete milled (5"-6") after rubblization to lower grade to accommodate overlay. Crushed aggregate (3") placed prior to asphalt overlay.
4969	Sturgis Airport, KY, center 75' of runway	2013	41,667	6	HMA	4	First asphalt wedge for grade & slope.
4909	Griffiss Intl Airport, Rome, NY, T/W A east & T/W E	2014	35,531	17-18	HMA	5	Crushed aggregate (3+") placed prior to asphalt overlay.
5079	Whitehorse Airport, Yukon Territory, Canada, T/W A	2014	12,381	12	HMA	4	Crushed aggregate (variable) placed prior to asphalt overlay.
	Chhatrapati Shivaji International Airport, Mumbai, India, T2 Apron & taxiway	2014	132,249	16	РССР	20	"Black sand" layer (variable) placed prior to concrete overlay. Areas closer to terminal overlaid with asphalt.
5223	Coles County Memorial Airport, Mattoon, IL, R/W 11/29	2015	112,112	14	HMA	6	Crushed aggregate (2-6") placed prior to asphalt overlay.
5248	Griffiss Intl Airport, Rome, NY, T/W E	2015	8,675	17	HMA	5	Crushed aggregate (3") placed prior to asphalt overlay.
5621	Bydgoszcz Airport, Poland, Taxiways	2015	83,360	8	HMA		
5422	Griffiss Intl Airport, Rome, NY, T/W A & T/W B	2016	40,766	16-29	HMA	5	Crushed aggregate (variable thickness) placed prior to asphalt overlay.
5592	Brown Field Airport, San Diego, CA, R/W 8L-26R	2016	8,377	10	HMA	4	Asphalt treated base (variable thickness) placed prior to asphalt overlay.
5704	Griffiss Intl Airport, Rome, NY, T/W A & T/W B	2016	24,607	16-26.5	HMA	5	Crushed aggregate (variable thickness) placed prior to asphalt overlay.
5725	NAS Patuxent River, MD, Overrun area at 14 end of R/W 14-32	2016	5,360	9	HMA	3	
5784	Buffalo Niagara Int'l Airport, NY, 14 end of runway	2017	26,667	9	HMA	12	Crushed aggregate (variable thickness) placed prior to asphalt overlay.

on to lower grade to ate (2") placed prior to
prior to asphalt overlay.
on to lower grade to ate (2") placed prior to
blization to lower grade to
to lower grade to
on to lower grade to
blization to lower grade to
ie to weak subgrade.
s ahead of schedule.
to lower grade to
ubblization to lower
n to accommodate
1

Antigo Job #	Location	Year	Concrete Rubblized (square yards)	Thickness of Existing Concrete (inches)	Overlay Type	Overlay Thickness (inches)	Comments
6991	Willard Airport, s/o Champaign, IL, R/W 4-22	2021	98,728	16-21	HMA	9	Concrete milled 2"-3" after rubblization to provide a rubblized surface that is 9" below final grade.
6992	Coles County Memorial Airport, Mattoon, IL, T/W B	2021	31,935	14	HMA	4	Concrete milled partial depth after rubblization to lower grade to accommodate overlay.
7055	Plattsburgh Intl Airport, NY, R/W 17-35	2021	228,762	14	HMA	5	Concrete milled 1" after rubblization. Some areas additional profile milled to obtain 5" asphalt at proposed grade.
7272	Norfolk Int'l Airport, VA, T/W C North	2021	15,420	16	HMA	6	Concrete milled 6" after rubblization to provide a rubblized surface that is 6" below final grade.
7357	Lask Airport, Poland	2021	15,562	10	HMA	7	Crushed aggregate (5-20 cm) and steel mesh (1.5 cm thick) placed prior to asphalt overlay.
7132	Griffiss Int'l Airport, Rome, NY, T/W E	2022	14,512	7	HMA	5	Crushed aggregate (6") placed prior to asphalt overlay.
7333	Walla Walla Regional Airport, WA, GA Apron	2022	22,200	8	HMA	4	
7339	Plattsburgh Intl Airport, NY, T/W A	2022	49,350	14	HMA	5	Concrete milled 5" after rubblization to provide a rubblized surface that is 5" below final grade.
7342	San Juan International Airport, Puerto Rico, T/W H	2022	15,200	16	HMA	5-11	
7394	Quincy Regional Airport, IL, R/W 4-22	2022	32,500	8-9	НМА	4	Crushed aggregate (4.5-6") placed prior to asphalt overlay.
7574	Westchester County Airport, NY, Aircraft Parking Apron	2022	2,083	9	HMA	5	
7333	Walla Walla Regional Airport, WA, GA Apron	2023	21,812	8	HMA	4	
7429	Plattsburgh Intl Airport, NY, T/W B	2023	28,684	14	HMA	5	Concrete milled 5" after rubblization to provide a rubblized surface that is 5" below final grade.
7556	Danville Regional Airport, VA, Apron, T/W D &E	2023	29,608	13-16	HMA	5	
7574	Westchester County Airport, NY, Apron, Hanger E-1	2023	4,235	9	HMA	5	
7657	Norfolk Int'l Airport, VA, R/W 5-23	2023	38,751	16	HMA	10	Concrete milled variable depth after rubblization to lower profile to allow for unform thickness asphalt overlay.

Antigo Job #	Location	Year	Concrete Rubblized (square yards)	Thickness of Existing Concrete (inches)	Overlay Type	Overlay Thickness (inches)	Comments
7766	Winnipeg Int'l Airport, Manitoba, Apron VIIA	2023	5,382	15	HMA	6	
7774	Oscoda-Wurtsmith Airport, MI, perimeter road	2023	13,422	5-6	HMA	5	
7892	Warsaw-Radom Airport, Poland, Aprons 3 & 5	2023	22,966	11	HMA	7	
7898	Nikola Tesla Airport, Belgrade, Serbia, R/W 12L/30R	2023	85,814	14	HMA	9	Crushed aggregate (6") placed prior to asphalt overlay.
7264	Kirtland AFB, Albuquerque, NM, T/W H & Pad 3	2024	25,582	15-20	HMA	7	
7730	Plattsburgh Int'l Airport, NY, T/W A & T/W B	2024	104,562	14	НМА	5	Concrete milled 5" after rubblization to provide a rubblized surface that is 5" below final grade.
7845	Quincy Regional Airport, IL, R/W 4/24	2024	28,174	8-9	НМА	4	Embankment and crushed aggregate placed on rubblized concrete prior to asphalt overlay.
7916	Norfolk International Airport, R/W 5/23 & Connectors	2024	39,639	17-23	HMA	7	
8147	Swidwin Air Base, Poland, R/W 11/29 & T/W	2024	185,317	11	HMA	9.5	
Last revised February 2025TOTAL SQUARE YARDS:5,693,8							